

A revolution in protection



- ISO 11612: 2008.
Clothing to protect against heat and flame
- ISO 11611: 2007.
Protective clothing for use in welding and allied processes
- EN 471 High Visibility.
GO/RT 3279: 2008
- EN 61482-1-1: 2009.
ATPV Electric Arc Protection $>8/\text{Cal}/\text{cm}^2$
- EN 61482-1-2: 2007.
Electric Arc Protection. Class 1 ('Box' Method)

TORAY

ThermGuardTM 

HIGH-VISIBILITY 

COLOUR SOLUTION

Toray Textiles Europe Ltd



Heat & Flame

ISO 11612: 2008



High Visibility

EN 471: 2003, GO/RT 3279: 2008



Electric Arc

EN 61482-1-1: 2009 Open arc ATPV

EN 61482-1-2: 2007 Box Method



Small Molten Metal Splashes

ISO 11611: 2007. Class 1



Antistatic Properties

EN 1149

Ultimate protection and visibility